



Common MPa to PSI Conversion Table

MPa	PSI
0.1 MPa	14.5 PSI
1 MPa	145 PSI
5 MPa	725 PSI
10 MPa	1,450 PSI
20 MPa	2,901 PSI
30 MPa	4,351 PSI
40 MPa	5,802 PSI
50 MPa	7,252 PSI
100 MPa	14,504 PSI
200 MPa	29,008 PSI
300 MPa	43,511 PSI
350 MPa	50,763 PSI
355 MPa	51,488 PSI